

Message Text

LIMITED OFFICIAL USE

PAGE 01 ANKARA 05044 110519Z
ACTION SY-05

INFO OCT-01 EUR-12 ISO-00 /018 W
-----082041 112227Z /14
R 101246Z JUL 78
FM AMEMBASSY ANKARA
TO AMEMBASSY ATHENS
INFO SECSTATE WASHDC 2565

LIMITED OFFICIAL USE ANKARA 5044

ATHENS FOR TSO

DEPT FOR A/SY/OPS/T

E.O. 11652: NA
TAGS: ASEC
SUBJ: 1976 COM VEHICLE-CHRYSLER

1. IN TAKING COM CHRYSLER TO BALGAT FOR NOISE
COMING FROM LEFT FRONT, THE BOLT AND RUBBER
BUSHING HOLDING LEFT FRONT TIE ROD END WERE MISSING.
TEMPORARILY REPAIRED BY BALGAT MAINTENANCE. IN
CHECKING FRONT END, FOLLOWING PARTS SHOWING
EXTREMELY HEAVY WEAR AND SHOULD BE REPLACED:

- A. BEARING, SECTOR SHAFT, POWER STEERING 1 EA
- B. OIL SEAL, SECTOR SHAFT, POWER STEERING 1 EA
- C. BALL JOINT, L H SIDE, LOWER 1 EA
- D. BALL JOINT, R H SIDE, LOWER 1 EA
- E. BALL JOINT, UPPER 2 EA

LIMITED OFFICIAL USE

LIMITED OFFICIAL USE

PAGE 02 ANKARA 05044 110519Z

- F. BUSHING KIT, UPPER CONTROL ARM 1 EA
- G. BUSHING KIT, LOWER CONTROL ARM 1 EA
- I. BUSHING KIT, STABILIZER
- J. END, TIE ROD, L H THREAD 2 EA

K. END, TIE ROD, R H THREAD 2 EA

L. STEERING RELAY ARM 1 EA

M. IDLER ARM ASSEMBLY 1 EA

N. STEERING ARM ASSEMBLY 1 EA

2. MAINTENANCE PERSONNEL AT BALGAT FEEL THAT
EXTREMELY HEAVY WEAR ON ABOVE PARTS IS RESULT OF
FACT VEHICLE DOES NOT HAVE HEAVY DUTY SHOCKS.
SHOCKS HAVE JUST BEEN RECEIVED AND WILL BE INSTALLED
ON CAR. REQUEST TWO EACH FRONT AND REAR SHOCKS AS
SPARES.
DILLON

LIMITED OFFICIAL USE

NNN

Message Attributes

Automatic Decaptioning: X
Capture Date: 01 jan 1994
Channel Indicators: n/a
Current Classification: UNCLASSIFIED
Concepts: n/a
Control Number: n/a
Copy: SINGLE
Draft Date: 10 jul 1978
Decaption Date: 01 jan 1960
Decaption Note:
Disposition Action: RELEASED
Disposition Approved on Date:
Disposition Case Number: n/a
Disposition Comment: 25 YEAR REVIEW
Disposition Date: 20 Mar 2014
Disposition Event:
Disposition History: n/a
Disposition Reason:
Disposition Remarks:
Document Number: 1978ANKARA05044
Document Source: CORE
Document Unique ID: 00
Drafter: n/a
Enclosure: n/a
Executive Order: N/A
Errors: N/A
Expiration:
Film Number: D780284-0439
Format: TEL
From: ANKARA
Handling Restrictions: n/a
Image Path:
ISecure: 1
Legacy Key: link1978/newtext/t19780781/aaaacqhi.tel
Line Count: 78
Litigation Code IDs:
Litigation Codes:
Litigation History:
Locator: TEXT ON-LINE, ON MICROFILM
Message ID: 4a94e378-c288-dd11-92da-001cc4696bcc
Office: ACTION SY
Original Classification: LIMITED OFFICIAL USE
Original Handling Restrictions: n/a
Original Previous Classification: n/a
Original Previous Handling Restrictions: n/a
Page Count: 2
Previous Channel Indicators: n/a
Previous Classification: LIMITED OFFICIAL USE
Previous Handling Restrictions: n/a
Reference: n/a
Retention: 0
Review Action: RELEASED, APPROVED
Review Content Flags:
Review Date: 14 jun 2005
Review Event:
Review Exemptions: n/a
Review Media Identifier:
Review Release Date: n/a
Review Release Event: n/a
Review Transfer Date:
Review Withdrawn Fields: n/a
SAS ID: 2075471
Secure: OPEN
Status: NATIVE
Subject: 1976 COM VEHICLE-CHRYSLER
TAGS: ASEC
To: ATHENS
Type: TE
vdkgvwkey: odb://SAS/SAS.dbo.SAS_Docs/4a94e378-c288-dd11-92da-001cc4696bcc
Review Markings:
Sheryl P. Walter
Declassified/Released
US Department of State
EO Systematic Review
20 Mar 2014
Markings: Sheryl P. Walter Declassified/Released US Department of State EO Systematic Review 20 Mar 2014